

## Clamps for brush-holders




Abb.1

Abb.2

Abb.3

Order No.	B x H x T	D	G	C	K	M1	M2	Abb.
KST13/12	22x30x12	13/10	--	11	18	M5	M6	1
KST16/15	25x32x15	16/13	--	15	18	M5	M5	1
KST20/15	30x40x15	20	--	15	24	M5	M5	1
KST13/12 L	29x69x12	13/10	--	13	50	M6	M6	2
KST16/14	36x70x14	16/13	47	13	50	M6	M6	3

Should you need a different type of clamp please indicate the following measures:

Bore (D): \_\_\_\_\_  
 Width (T): \_\_\_\_\_  
 C : \_\_\_\_\_  
 Height (K): \_\_\_\_\_  
 Terminal M1: \_\_\_\_\_ M2: \_\_\_\_\_  
 Riefelung : Yes / No

Please choose one of the figures (Abb.1 – Abb.3) or send us a photo.

(info@marl-industrievertretungen.de)